

GE Industry Sein & Services

April 24, 1991

APR 2 9 1991

AGCW-SEATTLE

Mr. Dan Peters ASH GROVE CEMENT COMPANY 3801 E. Marginal Way Seattle, WA 98314

> SUBJECT: HAZARDOUS WASTE MANIFEST NO. 28602 GENERAL ELECTRIC TRACKING NO. 22286

Dear Mr. Peters:

Attached please find the original copy of the Hazardous Waste Manifest, signed by our representative upon receipt of your material at our PCB Decommissioning Facility in-Portland. Please keep this record to establish the proper disposal of your PCB material.

We will provide you with copies of the Manifest when this material is sent out for final disposition. These copies will be signed by the ultimate disposer and our cover letter will reference the above captioned G.E. TRACKING NUMBER so that you will have a record of the material from the time it left your premises until it is properly disposed of.

Should you have any questions, please do not hesitate to call me at (503) 221-5098.

K Tortes

Sincerely

Facility Supervisor Portland Oregon

Attachment SKP/jr/ USEPA SF

1261

	UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US	ART 761	Manifes Document - 2866	1 2. No. 2.	Page I of 1	Infarma not requ	tion in th uired by f	e shaded areas ederal law.	s is	
1	3. Generator's Name and Mailing Address	WAD OD	924 8616		Α.	A. State Manifest Document Number					
4	ASH GROVE CEMENT COMPANY										
	3801 E. MARGINAL WAY Generator's Phone (206 823 5596	,	, WA 98314			B. State Generator's ID					
<u> </u>	5. Transporter 1 Company Name		6. US EPA ID Number			C. State Transporter's ID D. Transporter's Phone 583-221-5898					
	GENERAL ELECTRIC COMPANY		ORD 989 833 537			D. Transporter's Phone 583-221-3898 E. Stale Transporter's ID					
11	7. Tronsporter 2 Company Name—					F. Transporter's Phone					
Įŀ.	9. Designated Facility Name and Site Address		10. US EPA ID Number			G. State Facility's ID					
11	GENERAL ELECTRIC COMPANY										
$\ \cdot\ $	2535 NW 28TH AVE.					H. Facility's Phone					
1]	PORTLAND , OREGON 97210		. 0RD .980 .833 .537			2503-221-5098 (Carana)					
	US DOT Description (Including Proper Shipping Name, Hazard Class HM		ss. end ID Number)		Cantaine la. Tyj	İ	13. Total Quantity	14. Unit Wt/Val	l. Waste No.		
Ш	Hazardous Substance SC			_ + -			K	W001=	21 1: 127		
$\ \ $	ORM-E NA 9188 RR		2	2 5	ドノ	3409	,	7001			
Ĭŀ	(Polychlorinated Biphe Hazardous Substance 74			 	<u> </u>	+ -	· · · ·	+			
GEN	X DRM-E NA 9188 RQ	,,,,,,		۰۰۱	ء ا د		7,				
E	(Polychlorinated Biphe	enyls)		14	بے ج	m .	204	K	wol		
R A T	Hazardous Substance							1.5	- 1		
Ŏ.	X ORM-E NA 9188 RQ			ĺ							
R I	(Polychlorinated Biphe			<u> </u>		<u> </u>	<u> </u>		• 7-1		
11	Hazardous Substance X ORM-E NA 9188 RQ			- 1				7	· (1)		
П	(Folychlorinated Biphe	enyls)			. .						
	1. Additional Descriptions for Materials Listed Above				K	Hondling	Codes for	Wastes Li	l Above		
	標準하다. 그렇게 되어 하는 그 교육 항략이 충표됐다고 바퀴봤었죠는 어렸다는 소리, 바로 보면 쌓인하다고 하는 그 그 때문										
	Dike and contain spills. Avoid contact with skin. Alternate TSDF: Return To Benerator										
	and ternate pour preturn 100										
	5. Special Handling Instructions and Additional In	***	24 HR EMERGENCY RESPONSE					ISE			
1	A) ALL MATERIAL <50PPM BY						(8 80) 635-8918 EXT. 66				
$\left\ \cdot \right\ $	D) ALL MATERIAL LEOPPM			SEE GL	IIDE	NO. 31	- ATT	ACHED			
	16. GENERATOR'S CERTIFICATION: I hereby disclore that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed,										
$\ \ $	marked, and lobeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If a majorge quantity generator, I certify that I have a program in place to reduce the volume and taxicity of waste generated to the degree I have determined to be economically practicable.										
$\ \cdot\ $	and that those selected the proticable method of treatment, starage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good forth effort to minimize my waste generation and select the best waste management method that is available to me and that I can										
	offord										
7	Printed/Typed Name		Signature	mil ?	T	74				ear	
' T 1	7. Transporter 1 Acknowledgement of Receipt of A	Agterials	<i></i>	- Company	<u>, </u>	MA	<u> </u>	10	4 19 9	<u>}</u>	
	Printed/Typed Name	Signature	1		11	·	M	onth Day Ye	ear		
S	William CHESCER	,	mile	1.1		/	<u>-</u>	Ы	4199		
ខ្លុំ	8. Transporter 2 Acknowledgement of Receipt of A	Naterials									
RANSPORTER	Printed/Typed Name		Signature						anih Day Yi	eo:	
-	19. Discrepancy Indication Space								-		
	·										
FAC			•								
۲,	20 Facility Course - Consideration of marine 41										
20. Focility Owner or Operator: Certification of receipt of hazordous materials covered by this manifest except as noted in Item 19.											
' [Printed/Typed Name	~ / ₁ _	Signature	1 1	1	•	/	м	onth Day Y	g,	
	Printed/Typed Name	RICHSU	N Mag	fact	Es	<u>s k</u>	an_	4	4239	· /	
				-1							
					OR .						